

FITNESS CERTIFICATE

TO be filled by the Inspecting Officer (Assistant Engineer)
(Re: G.O. Ms.20/70/PWD Dt. 23-01-1970)

1. Name of officer : Sreekanth. K P
2. Name of School : Majma'a Central School, Kavanur
3. Location with name of Educational District/ Sub. District : Kavanur (Sub. Dist. Areacode)
4. Classification of Building as specified in column 4 of the Application for fitness certificate and size. : R.C.C. building
 1. 6.10 x 6.10 x 3.70 - 9 Nos Class room (Ground floor)
 2. 18.40 x 8.20 x 3.70 -1Nos library room(Ground floor)
 3. 9.25 x 6.10 x 3.70 - 1 Nos Class room (Ground floor)
 4. 9.25 x 6.10 x 3.70 - 9 Nos Class room (First floor)
 5. 9.25 x 6.10 x 3.70 - 9 Nos Class room (Second floor)
 6. 2.20 wide Verandah in all floors
 7. 3.05 x 6.10 - 2 Staircases
5. Period for which the Certificate is issued : 2021-22
6. Nature of defects , if any
 - a) Foundation and basement : Nil
 - b) Super Structure : Nil
 - c) Doors and windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous (cracks if any) : Nil
7. Any major defects noticed which will render the Building unsafe in any manner : No
8. Whether maintenance work have been done Properly. : Yes
9. Whether the structure is sound or note for conducting Classes : Yes, Sound for conducting Classes under normal wind and weather condition

Note:- 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on 14.06.2021 and found to be fit to conduct classes for the period 2021 -22 for the reason stated above.

Place: Kavanur
Date: 16.06.2021




ASSISTANT ENGINEER
Assistant Engineer
LSGD Section
Kavanur Gramapanchayath